


鑄造業

鑄造作業安全衛生管制點

| 部 門 | 小帽 安全帽 | 護目鏡 | 護目鏡/面罩 (遮光) (焊接面罩) | 耳罩 (耳塞) | 呼吸 防護具 P型活性碳 R型有機溶劑 | 高溫 防噴 護具 | 背負式 安全帶 | 棉紗 手套 | 有機溶劑 用手套 | 焊接 手套 | 安全鞋 足部防護 |
|------------|-----------|-----|--------------------------|------------|------------------------------|----------------|------------|----------|-------------|----------|-------------|
| 鑄造電爐區 | ● | | ● | ● | ● | ● | | | | | ● |
| 鑄造造型區 | ● | ● | | ● | ● | | | ● | | | ● |
| 鑄造澆注區 | ● | | ● | ● | ● | ● | | | | | ● |
| 鑄造後處理區 | ● | ● | | ● | ● | | ● | | | | ● |
| 鑄造堆高機駕駛 | ● | | | ● | ● | | ● | | | | ● |
| 鑄造工務 | ● | ● | | ● | ● | | ● | | | | ● |
| 鑄造工務(焊接作業) | ● | ● | ● | ● | ● | | | | ● | | ● |
| 工務高空作業 | ● | | | ● | ● | ● | | | ● | | ● |
| 品技焊補班 | ● | | ● | ● | ● | | | | ● | | ● |
| 銷管砂芯區 | ● | ● | | | ● | | | ● | | | ● |



護具種類



區域風險 警示標示



職業危害 警示標示




鑄造業

研磨作業安全衛生管制點

| 部 門 | 小帽 安全帽 | 護目鏡 | 面罩 | 耳罩 (耳塞) | 呼吸 防護具 <small>P型活性碳 R型有機溶劑</small> | 工作用 圍裙 袖套 | 棉紗 手套 | 泡油 手套 防燙 手套 | 安全鞋 |
|------------|-----------|-----|----|------------|--|-----------------|----------|----------------------|-----|
| 整理 洗 砂 | ● | ● | | ● | ● | ● | | ● | ● |
| 整理 生 產 車 間 | ● | ● | ● | ● | ● | ● | ● | ● | ● |
| 整理 泡 油 | ● | ● | | ● | ● | ● | | ● | ● |
| 整理 堆高機駕駛 | ● | ● | | ● | ● | | ● | | ● |
| 整理 品 保 | | ● | | ● | | ● | | | ● |

護具種類



區域風險 警示標示



職業危害 警示標示



鑄造業

加工噴塗作業安全衛生管制點

| 部 門 | 安全帽 | 護目鏡 | 呼吸 防護具 <small>R型有機溶劑</small> | 防毒面具 <small>(有機溶劑)</small> | 工作用 圍裙 | 泡油 手套 | 棉紗 手套 | 安全鞋 |
|----------|-----|-----|------------------------------------|-------------------------------|-----------|----------|----------|-----|
| 加工 生產車間 | | ● | | | ● | ● | | ● |
| 加工 噴塗車間 | | ● | | ● | ● | ● | | ● |
| 加工 組裝車間 | | | ● | | ● | | ● | ● |
| 加工 清 洗 線 | | | ● | | ● | ● | | ● |
| 加工 品 保 | | ● | ● | | | ● | ● | ● |
| 加工 堆高機駕駛 | ● | | ● | | | ● | ● | ● |
| 加工 工 務 | ● | ● | ● | | | ● | ● | |

護具種類



區域風險 警示標示



職業危害 警示標示

